



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-160729

PCN Date: 16-DEC-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: (Text limited to 120 characters)
Heat shrink tube

Description of Changes
As part of an ongoing and regular cleanup activity TE has identified several unused part numbers sitting in the heat shrink tubing Global Product Line 715

Reason for Changes:

PCN Attributes:	
Product Category: Heat Shrink Tubing	Kind of Change: Status Change
Change Feature: Discontinuance	Potential Customer Impact:
Remarks:	

Estimated Dates:	
Last Order Date (Obsolete Parts Only): 17-DEC-2022	First Ship Date of Changed Items (Changed Parts Only):
Last Ship Date of Changed Items (Obsolete Parts Only): 17-DEC-2022	Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
006351H001	YES		7-1190048-2, VFP-21-1-2-STK-SM			
006351P003	YES		7-1190048-4, VFP-21-1-2-48IN-SM			
007871P001	YES		1190061-2, FP21-2-X-48IN			
013241H003	YES		9-1190103-1, HIX-VW1-1/4-0-STK-SM			
013241J002	YES		9-1190103-2, HIX-VW1-1/4-0-SP-SM			
018645J002	YES		7-1190145-2, HIX-VW1-1-1/2-0-SP-SM			
020633M002	YES		8-1190160-9, FP21-1/8-0-SP			
032047T004	YES		5-1190248-5, RNF-100-3/4-1L			
033961-000	YES		1-1190263-0, RNF-100-1-CL-SP-CS7312			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
035373-000	YES		4-1190273-3, RNF-100-1/8-RD-SP-CS7554			
036153P002	YES		2-1190279-2, VFP-21-3/64-9-48IN-SM			
042463-000	YES		6-1190325-3, RNF-100-3/16-CL-SP-CS7312			
0461394001	YES		5-1190354-0, VFP-3/8-9-SP	NB14614001		PBL parts superseded by Standard part
0517992002	YES		6-1190396-4, RP-4800-NO.1-4-STK	NB24782001		Sales UOM change.
0555824003	YES		1190424-6, RNF-100-1-1/4-GN-SP			
060537-000	YES		8-1190458-7, RNF-100-3/4-BU-FSP			
062931-000	YES		8-1190475-7, RNF-100-3/4-RD-SP-CS5006			
0719034001	YES		6-1190539-6, VFP-3/4-0-SP	NB14374001		PBL parts superseded by Standard part
090729N001	YES		1190665-8, FP21-3/4-9-SP			
098235P001	YES		3-1190719-2, FP21-1/8-9-48IN			
1-603338-0	YES		"664303P002", "FP21-1-0-48IN", "169-0860-00"			
102098-000	YES		2-1197993-8, VFP-1-1/2-6-SP	NB17724001		PBL parts superseded by Standard part
105309-000	YES		8-1190769-5, RNF-100-2-BK-SP-CS7465			
108587-000	YES		2-1190793-2, RNF-100-3/8-BU-SP-CS7554			
1159594001	YES		8-1190844-1, VFP-3/32-9-SP	NB20504001		PBL parts superseded by Standard part
1169474001	YES		9-1190851-9, VFP-1/4-0-BULK-SP	NB20024001		PBL parts superseded by Standard part
120917-000	YES		4-1190879-5, VFP-1-1/4-0-SP	NB17744001		PBL parts superseded by Standard part
121380-000	YES		5-1198936-8, RNF-100-3/32-RD-SP-CS5004			
125493-000	YES		1-1190912-4, VFP-3/8-6-FSP	NB14594001		PBL parts superseded by Standard part
132051N001	YES		8-1190959-7, FP21-1/2-9-SP			
1321614001	YES		5-1190960-2, VFP-1/16-9-SP	NB20014001		PBL parts superseded by Standard part

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
132359P007	YES		8-1190961-9, VFP-21-3/8-9-48IN-SM			
137093J001	YES		8-1190993-3, HIX-VW1-2-0-SP-SM			
139431-000	YES		1-1191011-7, RNF-100-3/4-BK-STK-CS5004			
140621-000	YES		5-1191019-6, RNF-100-3/64-WH-SP-CS5551			
145659-000	YES		4-1191052-0, RNF-100-3/16-YO-SP-CS7554			
1464834001	YES		8-1191058-2, VFP-3/32-0-SP	NB20424001		PBL parts superseded by Standard part
151125H001	YES		6-1191092-2, VFP-21-3/4-0-STK-SM			
151125P006	YES		6-1191092-8, VFP-21-3/4-0-4.375IN-SM			
152573-000	YES		7-1191102-2, RNF-100-3/8-WH-SP-CS7554			
155907-000	YES		3-1191126-7, RNF-100-3/32-CL-SP-CS7607			
174309-000	YES		8-1191267-1, VFP-1-9-FSP	NB14324001		PBL parts superseded by Standard part
186821-000	YES		2-1191356-1, VFP-1/2-0-FSP	NB14124001		PBL parts superseded by Standard part
187446-000	YES		6-1199162-1, RNF-100-3/8-WH-FSP-CS5004			
1994974001	YES		2-1191445-0, VFP-1/4-2-SP	NB20074001		PBL parts superseded by Standard part
2046014001	YES		8-1191482-2, VFP-1-9-SP	NB14344001		PBL parts superseded by Standard part
215589H001	YES		1-1191557-8, VFP-21-3/32-0-STK-SM			
215589J002	YES		1-1191557-9, VFP-21-3/32-0-SP-SM			
215589P005	YES		2-1191557-3, VFP-21-3/32-0-12IN-SM			
219599H001	YES		3-1191620-9, VFP-21-1/4-0-STK-SM			
219599P007	YES		4-1191620-4, VFP-21-1/4-0-12IN-SM			
2238005-6	YES					
229873P003	YES		5-1191689-0, VFP-21-1/2-9-48IN-SM			
237311-000	YES		7-1191744-0, VFP-3/64-2-SP	NB23744001		PBL parts superseded by Standard part

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
246123-000	YES		7-1191805-0, RNF-100-1/8-BK-SP-CS5868			
2509874002	YES		5-1191839-9, VFP-3/8-4-SP	NB14554001		PBL parts superseded by Standard part
253885J002	YES		7-1191858-6, HIX-VW1-3/32-0-SP-SM			
257084-000	YES		3-1199500-4, RNF-100-1/8-BK-STK-CS7224			
257105-000	YES		5-1191881-6, FP21-3/32-X-SP			
277107P005	YES		2-1192052-3, VFP-21-3/8-0-12IN-SM			
280249-000	YES		2-1192074-3, RNF-100-1/4-WH-SP-CS7554			
281591-000	YES		3-1192086-3, VFP-3/4-2-FSP	NB14394001		PBL parts superseded by Standard part
289581J002	YES		6-1192195-9, HIX-VW1-3/16-0-SP-SM			
289705-000	YES		5-1192196-4, RNF-100-1/2-YO-SP-CS7554			
289987-000	YES		6-1192198-2, RNF-100-1/4-BK-STK-CS5004			
291555-000	YES		1-1192211-0, VFP-2-2-SP	NB17774001		PBL parts superseded by Standard part
293561P003	YES		8-1192224-4, VFP-21-3/8-2-48IN-SM			
295413J002	YES		1-1192238-8, HIX-VW1-3/8-0-SP-SM			
3000574001	YES		8-1192272-4, VFP-3/8-6-SP	NB23804001		PBL parts superseded by Standard part
302739-000	YES		3-1192293-5, RNF-100-1/2-GY-SP			
317799P003	YES		5-1192407-8, SR-1500-NO.3-N3-6-50MM			
317848-000	YES		3-1199812-6, FP21-3/8-X-SP			
329073-000	YES		2-1192488-2, RNF-100-3/8-RD-SP-CS7554			
330665-000	YES		3-1192498-1, RNF-100-NO.338-CL-STK			
332803-000	YES		9-1197857-0, RNF-100-1.5MM-CL-STK			
339581-000	YES		8-1192562-6, RNF-100-3/8-BK-SP-CS7227			
3445474001	YES		5-1192594-9, VFP-1-1/2-0-SP	NB17694001		PBL parts superseded by Standard part

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3489734001	YES		8-1192625-1, VFP-1/4-4-SP	NB20084001		PBL parts superseded by Standard part
377135K007	YES		2-1192824-6, VFP-21-1/8-0-48IN-SM			
390849-000	YES		4-1192934-5, VFP-3/64-6-SP	NB16984001		PBL parts superseded by Standard part
391163-000	YES		3-1192936-2, RNF-100-NO.337-CL-STK			
394029-000	YES		9-1192955-9, RNF-100-3/8-CL-SP-CS7312			
397479-000	YES		1192981-3, VFP-1-1/2-2-SP	NB17704001		PBL parts superseded by Standard part
398339-000	YES		2-1192987-1, FP21-1/4-X-SP			
4033234001	YES		6-1193044-3, VFP-3/4-6-SP	NB15224001		PBL parts superseded by Standard part
406997P006	YES		6-1193070-1, VFP-21-1/2-2-48IN-SM			
407301-000	YES		8-1193072-6, VFP-3/8-9-FSP	NB14604001		PBL parts superseded by Standard part
4114612001	YES		1-1193103-6, RNF-100-NO.333-CL-STK			
415781P005	YES		6-1193133-5, SR-1500-NO.1-N1-6-27MM			
4183674002	YES		7-1193152-8, VFP-3/4-2-SP			
429793-000	YES		9-1193232-0, VFP-1/2-4-SP	NB14194001		PBL parts superseded by Standard part
444345-000	YES		4-1193339-1, VFP-1-6-FSP	NB14314001		PBL parts superseded by Standard part
452338-000	YES		7-1198934-2, RNF-100-3/32-VT-SP-CS5004			
465337-000	YES		1193489-3, RNF-100-3/4-YO-FSP			
467393P005	YES		4-1193503-2, VFP-21-3/32-9-48IN-SM			
487177J001	YES		4-1193645-8, HIX-VW1-3/64-0-SP-SM			
4989614001	YES		2-1193730-9, RNF-100-1/8-BK-BULK-SP			
500567-000	YES		2-1193742-5, VFP-3/8-0-FSP	NB14474001		PBL parts superseded by Standard part
503958L012	YES		9-1193803-1, TPEN-NR8-0-STK-CS5769			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5050094015	YES		7-1193814-4, RNF-100-3/16-VT-SP			
5050814014	YES		6-1193817-1, RNF-100-2-GN-SP			
505288L042	YES		4-1193823-0, RNF-100-3/64-WH-STKCS7156			
505289L146	YES		5-1193824-6, RNF-100-1/16-BKSTK-CS7224			
5052934161	YES		3-1193826-3, RNF-100-1/16-WH-SP-CS5004			
505293L102	YES		7-1193826-0, RNF-100-1/16-WH-STKCS5529			
505293M103	YES		7-1193826-1, RNF-100-1/16-WH-SP-CS7375			
505294J213	YES		3-1193828-0, RNF-100-3/32-BK-SP-SM			
505298L204	YES		3-1193832-1, RNF-100-3/32-WH-STKCS7224			
505298M148	YES		3-1193832-2, RNF-100-3/32-WH-SP-CS7375			
505300M037	YES		5-1193835-9, RNF-100-1/8-RD-SP-CS5529			
505301M083	YES		3-1193836-7, RNF-100-1/8-YO-SP-CS5529			
505303L132	YES		1-1193838-6, RNF-100-1/8-WH-STK-CS5529			
505303L212	YES		1-1193838-7, RNF-100-1/8-WH-STK-CS5551			
505304L157	YES		6-1193840-7, RNF-100-3/16-BKSTK-CS5529			
505305M036	YES		7-1193841-3, RNF-100-3/16-RD-SP-CS6162			
505308M104	YES		5-1193844-0, RNF-100-3/16-WH-SP-CS7075			
505308M181	YES		5-1193844-1, RNF-100-3/16-WHSPCS5004			
505309P454	YES		2-1193848-5, RNF-100-1/4-A1-BK-20MM			
505309P456	YES		2-1193848-7, RNF-100-1/4-A1-BK-30MM			
505313L117	YES		3-1193852-6, RNF-100-1/4-WH-STK-CS5529			
505313M225	YES		3-1193852-9, RNF-100-1/4-WH-SP-CS7465			
505314M378	YES		9-1193854-9, RNF-100-3/8-BK-SP-CS5074			
505315M040	YES		2-1193858-4, RNF-100-3/8-RD-SP-CS5533			
505316L197	YES		1-1193859-1, RNF-100-3/8-YO-STK-CS6162			
505318L073	YES		4-1193861-9, RNF-100-3/8-WH-STK-CS5529			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
505318L160	YES		5-1193861-0, RNF-100-3/8-WH-STKCS5004			
505319B255	YES		7-1193863-8, RNF-100-1/2-BK			
505319J257	YES		8-1193863-8, RNF-100-1/2-BK-SP-SM			
505319L259	YES		9-1193863-1, RNF-100-1/2-BK-STK-CS7224			
505319L439	YES		9-1193863-2, RNF-100-1/2-BK-STKCS5004			
505320M039	YES		7-1193865-2, RNF-100-1/2-RD-SP-CS5529			
505321L152	YES		6-1193866-6, RNF-100-1/2-YO-STK-CS6162			
505322M055	YES		8-1193867-9, RNF-100-1/2-BU-SP-CS5529			
505323L075	YES		5-1193868-3, RNF-100-1/2-WH-STK-CS5529			
505323L152	YES		5-1193868-4, RNF-100-1/2-WH-STK-CS5004			
505323M076	YES		5-1193868-5, RNF-100-1/2-WH-SP-CS5529			
505324J174	YES		7-1193870-2, RNF-100-3/4-BK-SP-SM			
505324L175	YES		7-1193870-3, RNF-100-3/4-BK-STK-CS5529			
505324M176	YES		7-1193870-4, RNF-100-3/4-BK-SP-CS5074			
505325P092	YES		4-1193872-9, RNF-100-3/4-A1-RD-55MM			
505328L194	YES		5-1193875-3, RNF-100-3/4-WH-STK-CS5006			
505328M195	YES		5-1193875-4, RNF-100-3/4-WH-SP-CS5529			
505329L252	YES		5-1193877-6, RNF-100-1-BK-STKCS5004			
505329M158	YES		5-1193877-7, RNF-100-1-BK-SP-CS5529			
505331L136	YES		1-1193879-3, RNF-100-1-YO-STK-CS5529			
505333L133	YES		4-1193881-9, RNF-100-1-WH-STK-CS6162			
505334J097	YES		3-1193883-3, RNF-100-1-1/2-BK-SP-SM			
505334L190	YES		3-1193883-5, RNF-100-1-1/2-BKSTKCS5004			
505334M188	YES		3-1193883-7, RNF-100-1-1/2-BKSPCS5004			
505339M063	YES		3-1193886-3, RNF-100-2-BK-SP-CS5004	NB18154001		UoM change from Menlo to Trutnov transfer

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
505343L033	YES		4-1193887-7, RNF-100-2-WH-STK-CS5529			
505344L030	YES		1193888-2, RNF-100-3-BK-STK-CS7224			
505344M031	YES		1193888-4, RNF-100-3-BK-SP-CS5529			
505344M069	YES		1193888-5, RNF-100-3-BKSPCS5004			
5053462024	YES		3-1193888-2, RNF-100-3-YO-STK			
505349L050	YES		4-1193889-0, RNF-100-4-BK-STKCS5004			
505349M027	YES		4-1193889-2, RNF-100-4-BK-SP-CS5529			
5053614015	YES		5-1193890-8, RNF-100-3-GN-SP			
505391M034	YES		6-1193891-4, RNF-100-3/16-GN-SP-CS5321			
5053964008	YES		9-1193891-4, RNF-100-3/64-VT-SP			
5053982024	YES		1-1193892-1, RNF-100-1/16-BN-STK			
5053992015	YES		2-1193892-8, RNF-100-1/16-OR-STK			
5054054019	YES		2-1193893-5, RNF-100-3/32-GY-SP			
5054064021	YES		4-1193893-0, RNF-100-1/8-BN-SP			
5054072011	YES		5-1193893-5, RNF-100-1/8-OR-STK			
5054094026	YES		8-1193893-5, RNF-100-1/8-GY-SP			
5054142012	YES		7-1193894-5, RNF-100-1/4-OR-STK			
5054154016	YES		"9-1193894-8"			
5054164023	YES		1-1193895-4, RNF-100-3/8-BN-SP			
5054174014	YES		3-1193895-6, RNF-100-3/8-OR-SP			
5054224013	YES		2-1193896-1, RNF-100-1/2-VT-SP			
5054252011	YES		6-1193896-6, RNF-100-3/4-OR-STK			
5054272012	YES		1193897-2, RNF-100-1-BN-STK			
5054314013	YES		5-1193897-4, RNF-100-1-1/2-BN-SP			
505441M037	YES		8-1193898-0, RNF-100-1/4-GN-SP-CS5006			
5057394003	YES		1193904-3, RNF-100-1-1/4-WH-SP			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5058604001	YES		2-1193905-3, RNF-100-1-1/4-BU-SP			
5058632005	YES		2-1193905-7, RNF-100-1-1/4-RD-STK			
5058654004	YES		4-1193905-1, RNF-100-1-1/4-YO-SP			
5058726037	YES		6-1193906-3, VERSAFIT-3/16-0-1IN			
505875M010	YES		6-1193907-5, VERSAFIT-1/4-9-SP			
506565J002	YES		1193930-8, HIX-VW1-1/16-0-SP-SM			
507002M045	YES		9-1193959-2, RNF-100-1/16-CL-SP-CS5868			
507003L069	YES		8-1193960-3, RNF-100-3/32-CL-STKCS5733			
5070044140	YES		1-1193961-5, RNF-100-1/8-CL-SP-CS7312			
507004L079	YES		9-1193961-1, RNF-100-1/8-CL-STK-CS6162			
507006L064	YES		9-1193963-9, RNF-100-1/4-CL-STK-CS6162			
507006M070	YES		1193964-2, RNF-100-1/4-CL-SP-CS5823			
507007L078	YES		1193965-7, RNF-100-3/8-CL-STK-CS5006			
507007M082	YES		1193965-9, RNF-100-3/8-CL-SP-CS5868			
507008L128	YES		2-1193966-6, RNF-100-1/2-CL-STK-CS6162			
507009L073	YES		6-1193967-1, RNF-100-3/4-CL-STK-CS6162			
507009L137	YES		6-1193967-2, RNF-100-3/4-CL-STKCS7250			
507009M078	YES		6-1193967-4, RNF-100-3/4-CL-SP-CS7312			
507010L066	YES		5-1193968-7, RNF-100-1-CL-STK-CS6128			
507011L073	YES		4-1193969-3, RNF-100-1-1/2CLSTK-CS7250			
507011M074	YES		4-1193969-6, RNF-100-1-1/2CL-SP-CS5533			
507012L029	YES		9-1193969-6, RNF-100-2-CL-STK-CS7250			
507012M030	YES		9-1193969-8, RNF-100-2-CL-SP-CS7312			
507013L017	YES		2-1193970-9, RNF-100-3-CL-STK-CS7250			
507201M006	YES		1193972-8, RNF-100-1-1/4-CL-SPCS7312			
514393-000	YES		8-1194040-9, RNF-100-1/2-RD-SP-CS7554			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
519347-000	YES		4-1194075-4, VFP-1/2-6-FSP	NB14224001		PBL parts superseded by Standard part
525326-000	YES		9-1198114-7, RNF-100-1/4-RD-STK-CS7675			
529869H001	YES		1194161-4, VFP-21-1-0-STK-SM			
533409-000	YES		5-1194187-7, RNF-100-3/8-BU-FSP			
536753-000	YES		3-1194213-2, RNF-100-1/8-YO-SP-CS7554			
537019-000	YES		1194215-6, RNF-100-1/8-BK-30MM			
543957P007	YES		1-1194267-0, SR-1500-NO.2-N2-6-45MM			
570898-000	YES		1-1198935-0, RNF-100-3/32-GN-SP-CS5004			
576143P001	YES		2-1194571-4, FP21-1/2-9-STK			
584727-000	YES		3-1194630-1, VFP-1-4-SP			
589865-000	YES		9-1194666-8, VFP-2-4-SP	NB17784001		PBL parts superseded by Standard part
590417-000	YES		7-1194670-1, RNF-100-1-1/4-WH-SPCS7312			
590529-000	YES		5-1194671-2, RNF-100-1/2-RD-SP-CS7465			
5906772001	YES		7-1194672-6, RNF-100-NO.334-CL-STK			
596815-000	YES		2-1194720-3, VFP-3/4-4-FSP	NB14414001		PBL parts superseded by Standard part
600510-000	YES		7-1198933-3, RNF-100-1/4-A1-YO-SP			
602739-000	YES		9-1194770-3, RNF-100-2-BK-SP-CS7443			
603346-1	YES		"022429P001", "FP21-3/8-X-48IN"			
6060114001	YES		4-1194794-9, RNF-100-3/8-BK-BULK-SP			
633849J002	YES		7-1195013-6, HIX-VW1-3/4-0-SP-SM			
634615-000	YES		9-1195018-1, VFP-1/2-0-BULK-SP			
6372954001	YES		5-1195038-9, VFP-3/8-2-SP	NB23794001		PBL parts superseded by Standard part
643616-000	YES		3-1198935-1, RNF-100-3/32-BN-SP-CS5004			
664303M001	YES		1195235-3, FP21-1-0-SP			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
683239H001	YES		7-1195369-7, VFP-21-1/8-9-STK-SM			
689829J002	YES		1195417-9, VFP-21-2-0-SP-SM			
689829P005	YES		1-1195417-2, VFP-21-2-0-48IN-SM			
690661-000	YES		9-1195422-3, VERSAFIT-1/8-0-50MM			
6938834001	YES		7-1195444-5, VFP-3/4-9-SP	NB14454001		PBL parts superseded by Standard part
6990474001	YES		8-1195484-9, VFP-2-9-SP	NB17794001		PBL parts superseded by Standard part
707357-000	YES		1-1195545-5, RNF-100-1/2-CL-STK-CS7312			
708275-000	YES		4-1195551-0, VFP-2-6-SP			
717539H001	YES		8-1195612-9, VFP-21-1/2-0-STK-SM			
717539J002	YES		9-1195612-0, VFP-21-1/2-0-SP-SM			
717539P008	YES		9-1195612-6, VFP-21-1/2-0-4IN-SM			
7297334001	YES		1195701-3, VFP-3/8-0-SP	NB14494001		PBL parts superseded by Standard part
729937-000	YES		6-1195702-8, VFP-3/4-6-FSP	NB14434001		PBL parts superseded by Standard part
737004-000	YES		8-1197987-4, RNF-100-1-CL-FSP-CS7312			
7404454001	YES		4-1195779-4, VFP-1/4-6-SP	NB20114001		PBL parts superseded by Standard part
757477-000	YES		5-1195902-7, VFP-3/64-4-SP	NB16964001		PBL parts superseded by Standard part
774257-000	YES		5-1196029-3, RNF-100-3/8-GN-FSP			
791403H001	YES		5-1196129-4, VFP-21-3/16-0-STK-SM			
791403M004	YES		5-1196129-7, VFP-21-3/16-0-SP-SM			
791403P005	YES		5-1196129-8, VFP-21-3/16-0-12IN-SM			
791403P007	YES		6-1196129-0, VFP-21-3/16-0-0.5IN-SM			
791403P008	YES		6-1196129-1, VFP-21-3/16-0-75MM-SM			
798993-000	YES		4-1197862-6, RNF-100-3/8-WH-STK-CS5551			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
828931-000	YES		9-1196472-9, VFP-1/2-4-FSP	NB14184001		PBL parts superseded by Standard part
849139-000	YES		4-1196621-1, VFP-3/4-0-FSP	NB14354001		PBL parts superseded by Standard part
852145-000	YES		2-1196643-6, VFP-3/8-4-FSP	NB14544001		PBL parts superseded by Standard part
863727-000	YES		4-1196726-3, RNF-100-3/8-WH-SP-CS5074			
875675-000	YES		2-1196812-8, RNF-100-1-CL-SP-CS7535			
884903-000	YES		3-1196886-1, VFP-3/8-2-FSP	NB14524001		PBL parts superseded by Standard part
9137814001	YES		1-1197095-7, VFP-1/2-6-SP			
9215794002	YES		3-1197150-8, VFP-1-2-SP	NB23554001		PBL parts superseded by Standard part
923757-000	YES		2-1197166-6, VFP-1-4-FSP	NB23564001		PBL parts superseded by Standard part
9340754001	YES		3-1197238-1, VFP-3/64-9-SP	NB16994001		PBL parts superseded by Standard part
946138-000	YES		9-1199506-9, RNF-100-3/8-VT-SP-CS5004			
951101-000	YES		1-1197355-8, RNF-100-3/16-RD-SP-CS7554			
967171-000	YES		6-1197478-0, RNF-100-1/2-CL-STK-CS7620			
967179P001	YES		6-1197478-7, FP21-3/16-9-48IN			
969117-000	YES		5-1197492-9, RNF-100-1/16-WH-STKCS5551			
9714154001	YES		1-1197509-3, VFP-3/64-0-SP	NB16934001		PBL parts superseded by Standard part
971681-000	YES		8-1197510-7, RNF-100-1/2-WH-SP-CS7554			
980937-000	YES		1197580-6, RNF-100-3/4-YO-SP-CS7554			
9814834001	YES		6-1197583-6, VFP-3/16-6-SP	NB20384001		PBL parts superseded by Standard part
992377-000	YES		8-1197675-3, RNF-100-1/4-YO-SP-CS7554			
9998214001	YES		5-1197729-9, VFP-1/2-9-SP	NB14244001		PBL parts superseded by Standard part

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
A62384-000	YES		6-1201922-6, RNF-100-3/4-BK-SP-CS7807			
A65752-000	YES		4-1201885-7, RNF-100-1/8-BK-SP-CS7797			
A76950-000	YES		3-1200479-3, RNF-100-3/8-WH-65MM			
A87326-000	YES		8-1202161-4, RNF-100-3-BK-STK-CS7250			
A98179-000	YES		3-1201562-7, VERSAFIT-1/4-9-2IN			
BM9739-000	YES					
C02643-000	YES		8-1201241-0			
C04348-000	YES		6-1201690-3, RNF-100-3/64-BK-STKCS7250			
C13257-000	YES		1-1201299-0, RNF-100-3/32-OR-SPCS5004			
C16906-000	YES		8-1202034-3, RNF-100-3/8-BK-STK-CS7387			
C21606-000	YES		5-1200701-1, RNF-100-3/16-WH-STKCS5592			
C28850-000	YES		5-1201550-8, RNF-100-090/105-WH-CSP			
C32783-000	YES		8-1202034-4, RNF-100-1/4-GY-SP-CS5004			
C41441-000	YES		9-1201922-7, RNF-100-3/16-WH-SP-CS7807			
C92102-000	YES		4-1201282-8, RNF-100-1/2-CL-FSPCS7312			
CA4833-000	YES		6-1899526-9, RNF-100-2-OR-SP			
CB1869-000	YES		RNF-100-1/2-BK-4.5IN			
CJ6363-000	YES		4-1899833-9, RNF-100-1-OR-FSP			
CL4285-000	YES		"RNF-100-3/32-BK-STK-CS5529"			
CL7721-000	YES		"INSL-22879-CCPT-5/8-6D-FSP"			
CL7723-000	YES		"INSL-22880-CCPT-1/2-6D-FSP"			
CM1137-000	YES		"RNF-100-1/4-YO-SP-CS7387"			
CM2865-000	YES		"INSL-23001-VFIT-3X-1-1/2-9-SP-"			
CM2960-000	YES					
CM3484-000	YES		"RNF-100-3/16-RD-SP-CS5533"			
CM5922-000	YES		"RNF-100-1/2-A1-BK-55MM"			
CM6968-000	YES		6-1899833-9, RNF-100-1/2-BK-150MM			
CM8332-000	YES					
CM9488-000	YES					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CM9610-000	YES		7-1899833-1, RNF-100-1/16-BK-45MM			
CM9611-000	YES		RNF-100-1/16-BK-110MM			
CM9933-000	YES		RNF-100-1/2-BK-515MM			
CN1085-000	YES					
CN3422-000	YES					
CN4288-000	YES		RNF-100-1/8-BK-STK-CS8794			
CN5307-000	YES					
CN5312-000	YES		RNF-100-1-BK-35MM			
CN7633-000	YES		RNF-100-3/16-GN-SP-CS5004			
CN7634-000	YES		RNF-100-3/16-RD-SP-CS5004			
CN8371-000	YES		RNF-100-3/8-WH-SP-CS5004			
CN8833-000	YES					
CP0293-000	YES		RNF-100-1/4-BK-1.25IN			
CP0294-000	YES		RNF-100-1/4-BK-2IN			
CP0295-000	YES		6-1899833-7, RNF-100-1/4-BK-4IN			
CP0960-000	YES					
CP2013-000	YES					
CP2329-000	YES					
CP4321-000	YES					
CP4854-000	YES		RNF-100-1-BK-135MM			
CR0866-000	YES					
CR1834-000	YES					
CR3007-000	YES					
CR8171-000	YES					
CS6003-000	YES		"RNF-100-0.543-BK-SP", "1899833-1"			
CS6422-000	YES					
CU0518-000	YES		RNF-100-1.3MM-CL-SP			
CU3549-000	YES		RNF-100-3/16-BK-60MM			
CV4177-000	YES					
CV4178-000	YES					
CV4179-000	YES					
CV4181-000	YES					
CV4183-000	YES					
CV4185-000	YES					
CV4187-000	YES					
CV4188-000	YES					
CV4189-000	YES					
CV4192-000	YES					
CV4194-000	YES					
CV4195-000	YES					
CV4198-000	YES					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV4201-000	YES					
CV4205-000	YES					
CV4209-000	YES					
CV4210-000	YES					
CV4211-000	YES					
CV4212-000	YES					
CV4213-000	YES					
CV4214-000	YES					
CV4215-000	YES					
CV4216-000	YES					
CV4218-000	YES					
CV4219-000	YES					
CW3362-000	YES					
CW7197-000	YES					
CX4531-000	YES					
CX5930-000	YES					
CY3685-000	YES					
CY3686-000	YES					
CY9277-000	YES		RNF-100-3/16-BK-40MM			
CZ4361-000	YES		RNF-100-1/4-RD-30MM			
CZ8200-000	YES		VERSAFIT-3/4-0-2.25IN			
CZ8951-000	YES		RNF-100-1-BK-1.25IN			
D14887-000	YES		2-1200478-7, RNF-100-3/16-BK-SP-CS7387			
D15033-000	YES		RNF-100-1/2-BK-490MM			
D48425-000	YES		7-1202052-3, RNF-100-NO.342-CL-STK			
D71856-000	YES		3-1201923-8, RNF-100-1/8-WH-SP-CS7807			
E20260-000	YES		3-1202073-9, RNF-100-1/4-VT-SP-CS5004			
E28898-000	YES		6-1201923-1, RNF-100-1/8-BK-SP-CS7807			
E50610-000	YES		7-1201326-3, VFP-1-1/2-4-SP	NB17714001		PBL parts superseded by Standard part
E70690-000	YES		8-1201456-4, RNF-100-3/8-BK-FSP-CS5004	NB22674001		UoM and mfg. location change
E93634-000	YES		1-1200701-5, RNF-100-1/8-BK-STK-CS5592			
EF5091-000	YES					
EF5737-000	YES					
EG0543-000	YES		RNF-100-3/64-VT-STK			
EG2104-000	YES					
EG4686-000	YES					
EG5869-000	YES					
EG8033-000	YES					
EG8106-000	YES		RNF-100-1-1/2-BK-85MM			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EG9112-000	YES					
EJ2978-000	YES		RNF-100-0.112-CL-STK			
EK0731-000	YES					
EL6095-000	YES		RNF-100-1/2-BU-60MM			
EM1153-000	YES					
EM1154-000	YES					
EM4507-000	YES		TC-CAPS-4005-8-CS5482			
EM5333-000	YES		VERSAFIT-1/2-0-32.25IN			
EM5940-000	YES					
EM6957-000	YES					
EM7594-000	YES		FTS-1030-X-SP			
EP0791-000	YES					
EP6327-000	YES					
EP6329-000	YES					
EP6330-000	YES					
EP6331-000	YES					
EP6332-000	YES					
EP6333-000	YES					
EP6334-000	YES					
EP6335-000	YES					
EP6338-000	YES					
EP6379-000	YES					
EP6386-000	YES					
EP6388-000	YES					
EP7585-000	YES					
EP7586-000	YES					
EP7588-000	YES					
EP7589-000	YES					
EP7591-000	YES					
ER1793-000	YES					
E11826-000	YES		3-1200396-6, RNF-100-3/8-BK-FSP-CS7743			
F39117-000	YES		8-1201442-2, VERSAFIT-5/8-4-FSP			
F73274-000	YES		3-1200082-3, VERSAFIT-1-1/2-0-SPCS7646			
F84496-000	YES		1200968-7, TPEM-NR7-0-STK-CS7760			
F99253-000	YES		RNF-100-1/2-BK-3IN			