

End of Life Notification

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. Unavailability of component parts, generally of an earlier technology or an older design, can cause the obsolescence of outdated product families.

We sincerely appreciate your business and will make every effort to work with you during your transition to the new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies. All products now being discontinued are available for an end-of-life last time buy.

We have recommended a suitable replacement for your convenience on most of the end-of-life models. If you have any questions or need specific application assistance, please contact us (you may visit <https://www.artesyn.com/contact>. Email to productsupport.ep@Artesyn.com or call 1- 888-412-7832) or your local sales representative to assist you. Thank you for your continued patronage.

The following series/models have been marked as EOL:

Model No	Product Rank	Replacement Model	Replacement Info	LTB start	LTB end
CXA10-48S3V3J	L	AEE04F36-LS	Note; Higher output current rating with metal casing and fully potted.	04/30/2018	05/18/2018
CXA10-48S3V3-SJ	L	AEE04F36-LS	Note; Higher output current rating with metal casing and fully potted.	04/30/2018	05/18/2018
LES20A24-3V3EJ	L	AVO100-36S3v3B-6L	Wider input voltage range	04/30/2018	08/30/2018
LES20A24-3V3RAJ	E	AVO100-36S3v3B-6L	Wider input voltage range	04/30/2018	08/30/2011
LES20A24-3V3REJ	L	AVO100-36S3v3B-6L	Wider input voltage range	04/30/2018	08/30/2018
LES20A24-3V3SJ	L	AVO100-36S3v3B-6L	Wider input voltage range	04/30/2018	08/30/2018
LES50A48-1V2REJ	L	AVO100-48S1V2		04/30/2018	08/30/2018
LES50A48-1V2RENJ	L	AVO100-48S1V2		04/30/2018	08/30/2018
LES40A48-2V5REJ	L			04/30/2018	08/30/2018

LQD25A48-5V03V3REJ	L			04/30/2018	08/30/2018
LQS30A24-3V3RSJ	L	AVO100-36S3v3B-6L	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS40A48-5V0EJ	L	AVO200-48S05-6L	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS40A48-5V0REJ	L	AVO200-48S05-6L	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS40A48-5V0RENJ	L	AVO200-48S05-6L	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS50A48-1V2EJ	L	AVO100-48S1V2	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS50A48-1V2RAJ	L	AVO100-48S1V2	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS50A48-1V2REJ	L	AVO100-48S1V2	1/8th brick that fits on the 1/4 brick footprint	04/30/2018	08/30/2018
LQS50A48-1V5AJ	L			04/30/2018	08/30/2018
LQS50A48-1V5REJ	L			04/30/2018	08/30/2018
LQS50A48-1V8REJ	L			04/30/2018	08/30/2018
LQS50A48-2V5EJ	L			04/30/2018	08/30/2018
LQS50A48-2V5REJ	L			04/30/2018	08/30/2018
LQS50A48-3V3EJ	L	ADO300-48S3V3-6L	1/8th brick that fits on the 1/4 brick footprint. Slightly higher in power rating	04/30/2018	08/30/2018
LQS50A48-3V3REJ	L	ADO300-48S3V3-6L	1/8th brick that fits on the 1/4 brick footprint. Slightly higher in power rating	04/30/2018	08/30/2018
LQS60A48-3V3RAJ	L	ADO300-48S3V3-6L	1/8th brick that fits on the 1/4 brick footprint.	04/30/2018	08/30/2018
LQS60A48-3V3REJ	L	ADO300-48S3V3-6L	1/8th brick that fits on the 1/4 brick footprint.	04/30/2018	08/30/2018
LQS80A48-1V5REJ	L			04/30/2018	08/30/2018

LQS80A48-1V8REJ	L			04/30/2018	08/30/2018
LQS80A48-2V5RAJ	L			04/30/2018	08/30/2018
LQS80A48-2V5REJ	L			04/30/2018	08/30/2018
LQS100A48-1V2RAJ	L			04/30/2018	08/30/2018
LQS100A48-1V2REJ	L			04/30/2018	08/30/2018
LQS100A48-1V5REJ	L			04/30/2018	08/30/2018
LQS100A48-1V8RAJ	L			04/30/2018	08/30/2018
LQS100A48-1V8REJ	L			04/30/2018	08/30/2018