

Date: June 26, 2017
To: Bussmann series PV10M photovoltaic fuse customers
Subject: End-of-life notice

Dear valued customer:

Effective June 1, 2017, we have discontinued offering the 10x38mm 1000Vdc 25A and 30A photovoltaic fuses. The affected catalog numbers are listed below along with their recommended replacements. Although the replacement offering is in a 14x51 mm package, it can be used as a replacement should the need arise.

End of Life	Replaced by
PV10M-25	PV-25A14F
PV10M-30	PV-32A14F

Should you need technical assistance in applying the recommended replacements, please contact our Application Engineering team toll-free at 1-855-278-7626, or email FuseTech@eaton.com.

Thank you for your support of Eaton's Bussmann series circuit protection products. Should you have any questions regarding this end-of-life notice, please contact your local Bussmann series product representative.

Best Regards,

Kevin Calzada
Product Manager
Eaton