

## Product Change/Obsolescence Notification

### TRIMPOT® PRODUCTS



June, 2013

### Bourns® Trimpot® Products

In July 2012, Bourns Trimpot Product Line announced the move of the manufacturing location for non-wirewound trimmer and modular contact Bourns® products in Product Change Notification (PCN) number T1214. Associated with the manufacturing moves announced in [PCN T1214](#) was the move or obsolescence of certain associated hardware products and design kits. At this time, Bourns is confirming the new manufacturing locations or obsolescence for the hardware and design kits listed below. There is no change to the form, fit or function of the hardware as a result of the change in manufacturing location for the listed hardware products.

Hardware Part Number	New Manufacturing Location	Date Moved to New Plant
<a href="#">H-28</a>	Costa Rica	Oct. 2012
<a href="#">H-82</a>	Costa Rica	Oct. 2012
<a href="#">H-83P</a>	Costa Rica	Oct. 2012
<a href="#">H-117P</a>	Costa Rica	Oct. 2012
<a href="#">H-115P</a>	Costa Rica	Oct. 2012
<a href="#">H-25</a>	Costa Rica	Nov. 2012
<a href="#">H-65P-1</a>	Costa Rica	Nov. 2012
<a href="#">H-58P</a>	Costa Rica	Nov. 2012
<a href="#">H-114P</a>	Costa Rica	Jan. 2013
<a href="#">H-116P</a>	Costa Rica	Jan. 2013

Design Kit Part Number	New Manufacturing Location	Date Moved to New Plant
H-814-2	Obsolete	Mar. 2012
H-840	Obsolete	Mar. 2012
<a href="#">H-839</a>	Taiwan	Jan. 2013
<a href="#">H-843</a>	Taiwan	Jan. 2013
<a href="#">H-851</a>	Costa Rica	Jan. 2013

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).