

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

## **Early Problem Notification CMEM\_TC.001: First Access to CMEM after Power-up**

N° 012/18

## Early Problem Notification CMEM\_TC.001: First Access to CMEM after Power-up

Products affected:	Sales Name	SP N°	OPN	Package
	Please refer to 1_cip01218 attached			

### Detailed Change Information:

**Subject:** Early Problem Notification CMEM\_TC.001: First Access to CMEM after Power-up.  
Please refer to 4\_cip01218 attached

**Reason:** Functional Problem.

**Description:**

Old

- Not applicable (no previous release)

New

- Early Problem Notification CMEM\_TC\_001\_EPN\_v1\_0 (first release)

**Product Identification:** Not applicable (no change of product)

**Impact of Change:** Not applicable (no change of product)

**Attachments:**  
Affected product list: 1\_cip01218  
CMEM\_TC\_001\_EPN\_v1\_0: 4\_cip01218

**Intended start of delivery:** Not applicable

If you have any questions, please do not hesitate to contact your local Sales office.

Early Problem Notification CMEM\_TC.001: First Access to CMEM after Power-up



Sales Name	SP number	OPN	Package
SAK-TC1724ED-192F133HLAB	SP000906014	N.A.	PG-LQFP-144
SAK-TC1724F-192F133HL AB	SP000906012	TC1724F192F133HLABKXUMA1	PG-LQFP-144
SAK-TC1724F-192F133HR AB	SP000947156	TC1724F192F133HRABKXUMA1	PG-LQFP-144
SAK-TC1724F-192F133HR AC	SP001114336	TC1724F192F133HRACKXUMA2	PG-LQFP-144
SAK-TC1724N-128F133HL AB	SP000984884	TC1724N128F133HLABKXUMA1	PG-LQFP-144
SAK-TC1724N-192F133HL AB	SP000908726	TC1724N192F133HLABKXUMA1	PG-LQFP-144
SAK-TC1724N-192F133HR AC	SP001064674	TC1724N192F133HRACKXUMA1	PG-LQFP-144
SAK-TC1724N-192F80HL AB	SP000910206	TC1724N192F80HLABKXUMA1	PG-LQFP-144
SAK-TC1724N-192F80HR AB	SP000947148	TC1724N192F80HRABKXUMA1	PG-LQFP-144
SAK-TC1724N-192F80HR AB	SP001006930	N.A.	PG-LQFP-144
SAK-TC1724N-192F80HR AC	SP001113370	TC1724N192F80HRACKXUMA1	PG-LQFP-144
SAK-TC1724N-192F80HR AC	SP001113384	TC1724N192F80HRACKXUMA2	PG-LQFP-144
SAK-TC1728ED-192F133HLAB	SP000908730	N.A.	PG-LQFP-176
SAK-TC1728F-192F133HR AC	SP001093712	TC1728F192F133HRACKXUMA2	PG-LQFP-176
SAK-TC1728F-192F133HR AC	SP001109596	TC1728F192F133HRACKXUMA1	PG-LQFP-176
SAK-TC1728N-192F133HL AB	SP000908728	TC1728N192F133HLABKXUMA1	PG-LQFP-176
SAK-TC1728N-192F133HL AB	SP001329314	TC1728N192F133HLABKXUMA2	PG-LQFP-176
SAK-TC1728N-192F133HR AB	SP000947378	N.A.	PG-LQFP-176
SAK-TC1728N-192F133HR AC	SP001093714	TC1728N192F133HRACKXUMA2	PG-LQFP-176
SAK-TC1728N-192F133HR AC	SP001690940	TC1728N192F133HRACKXUMA3	PG-LQFP-176