

## PRODUCT DISCONTINUANCE NOTICE (PDN)

**PDN Number:** #[13-0026a](#)

Issue Date: **April 21, 2014**

Product(s) Affected: **See below**

Last Purchase Date: **July 28, 2014**

Last Shipment Date: **July 28, 2015**

**Reason for Discontinuing Listed Products:**

- Obsolete Design/Process Technology
- Obsolete Package/Assembly Technology
- No current or rapidly declining sales
- Other: *Demand volume is not sufficient enough to justify the continuation of these devices*

**Pericom (PSC) Contact:** [Raul Aman](#)

Title: [Quality Assurance Director](#)

Phone: [408 232-9100](#)

Fax: [408-434-1040](#)

eMail: [PCN\\_PD@pericom.com](mailto:PCN_PD@pericom.com)

-----  
-

**Pericom (PTI) Contact:** [Li Hua](#)

Title: [Quality Section Manager](#)

Phone: [86-21-64850576](#)

Fax: [86-21-64852181](#)

eMail: [PCN\\_PD@pti.com.cn](mailto:PCN_PD@pti.com.cn)

**\* Note:**

*Pericom would like to notify all customers that products listed below will be discontinued due to demand volume is not sufficient enough to justify the continuation of these devices*

*Pericom apologizes for any inconvenience this situation may cause.*

This is revision on the PDN #13-0026 (issue date: Nov 27, 2014). The recommend replacement parts are PT7V41283-A series and PT7V41284-A series.

Pericom Part Number	Comments for customers
PT7V4027WE	Replacement parts: PT7V41283-A (3.3V supply voltage application) and PT7V41284-A (5V supply voltage application) . Please contact cs@pti.com.hk
PT7V4027DE	
PT7V4027WF	

**Customer Acknowledgement:**

Customer: .....

Name: .....

Title: .....

Date: .....

E-Mail: .....

Phone: .....

Fax: .....

*Customers may use this form to acknowledge receipt of this notification, or can e-mail the Pericom contact noted above.*

**Customer Comments:** .....

Pericom Internal Use Only:

Location:     PSC             PTI             PSE-TW             PSE-SD

PSETW PDN: N/A