



## Product Change Notification / SYST-29VKTO359

---

### Date:

31-Mar-2023

### Product Category:

Clock and Timing - Clock Generation

### PCN Type:

Document Change

### Notification Subject:

Data Sheet - DSC557-03-04-05 - Multiple Output MEMS PCIe Gen1/2/3/4 Clock Generators

### Affected CPNs:

[SYST-29VKTO359\\_Affected\\_CPN\\_03312023.pdf](#)

[SYST-29VKTO359\\_Affected\\_CPN\\_03312023.csv](#)

### Notification Text:

SYST-29VKTO359

Microchip has released a new Datasheet for the DSC557-03-04-05 - Multiple Output MEMS PCIe Gen1/2/3/4 Clock Generators of devices. If you are using one of these devices please read the document located at [DSC557-03-04-05 - Multiple Output MEMS PCIe Gen1/2/3/4 Clock Generators](#).

**Notification Status:** Final

#### Description of Change:

Added a note to Section 5.1 "Package Marking Information" indicating some parts may be shipped with DSA on the package marking until that stock is depleted and the updated DSC package marking begins.

**Impacts to Data Sheet:** See above details.

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 31 Mar 2023

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

[DSC557-03-04-05 - Multiple Output MEMS PCIe Gen1/2/3/4 Clock Generators](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

DSC557-054444KI2  
DSC557-04333KI1  
DSC557-04444KI1  
DSC557-054444KI1  
DSC557-053344KL1T  
DSC557-053333KL1T  
DSC557-04444KL1  
DSC557-04444KL1T  
DSC557-04444KI1T  
DSC557-054444KI1T  
DSC557-054444KI0  
DSC557-054444KI0T  
DSC557-0333FI0  
DSC557-0334FI1  
DSC557-0343FI0  
DSC557-0344FI0  
DSC557-0344FI1  
DSC557-0343FI1  
DSC557-0333FI1  
DSC557-0333FL0  
DSC557-0333FE0  
DSC557-0341FE1  
DSC557-0344FE0  
DSC557-0344FE1  
DSC557-0344FL1  
DSC557-0333FE0T  
DSC557-0333FL0T  
DSC557-0341FE1T  
DSC557-0344FE0T  
DSC557-0344FL1T  
DSC557-0333FI0T  
DSC557-0344FI0T  
DSC557-0344FI1T  
DSC557-0343FI1T  
DSC557-0344FI1B  
DSC557-0333FI1T