

**Annoumcent of the
FA components
discontinuation**

**IN Better
Solution**

Panasonic
INDUSTRY

**Product Discontinuation Announcement of
LT4H Digital Timer, LT4H-L Digital Timer,
LC4H-S Electronic Counter (with pre-scale function)**

Dear valued customers,

This letter is to notify you that the Timer, Counter, other FA components products will be discontinued due to discontinuation of its main parts and aging production equipment which is difficult to continue the production. We apologize for any inconvenience and appreciate your kind understanding.

< End of order acceptance > End of December 2022

*Last delivery will be 6 months from the end of order date.

However, the delivery schedule may change depend on the order quantity.

< Maintenance period > End of December 2026

*In case of product failure/defect under manufacturers' liability during the warranty period, we will prepare the replacement.

*Parts will be prepared by considering above schedule.

However, depend on stocks and part suppliers' status, there is possibility we are unable to accept all orders. There is also possibility that we are unable to repair even within maintenance period, due to above reason.



Discontinuation on December 26th, 2022

< Discontinuation and recommended substitutes >


Discontinued product			Recommended substitute	
Product name		Series name		Number of models
Timer	Digital	LT4H Digital Timer (DIN□48)	18	There is no recommended replacement.
		LT4H-L Digital Timer (DIN□48)	6	
Counter		LC4H-S Electronic Counter (with pre-scale function)	28	

*Includes special ordered products and accessories and optional items

More than

Series	Model number	Part number	Recommended substitutes
LT4H Digital Timer  *Includes custom-made items.	LT4H8-AC240V	ATL5137	There is no recommended replacement.
	LT4H-AC240V	ATL5117	
	LT4H-AC240VS	ATL5187	
	LT4H8-AC24V	ATL5130	
	LT4H-AC24V	ATL5110	
	LT4H-AC24VS	ATL5180	
	LT4H8-DC24V	ATL5131	
	LT4H-DC24V	ATL5111	
	LT4H-DC24VS	ATL5181	
	LT4HT8-AC240V	ATL5127	
	LT4HT-AC240V	ATL5107	
	LT4HT-AC240VS	ATL5177	
	LT4HT8-AC24V	ATL5120	
	LT4HT-AC24V	ATL5100	
	LT4HT-AC24VS	ATL5170	
	LT4HT8-DC24V	ATL5121	
	LT4HT-DC24V	ATL5101	
	LT4HT-DC24VS	ATL5171	
LT4H-L Digital Timer  *Includes custom-made items.	LT4HL8-AC240V	ATL1137	There is no recommended replacement.
	LT4HL8-AC24V	ATL1130	
	LT4HL8-DC24V	ATL1131	
	LT4HLT8-AC240V	ATL1127	
	LT4HLT8-AC24V	ATL1120	
	LT4HLT8-DC24V	ATL1121	
LC4H-S Electronic Counter  *Includes custom-made items.	LC4H-PS-R4-AC240V	AEL5117PS	There is no recommended replacement.
	LC4H-PS-R4-AC240VS	AEL5187PS	
	LC4H-S-R4-24V	AEL5112S	
	LC4H-S-R4-24VS	AEL5182S	
	LC4H-S-T4-24V	AEL5102S	
	LC4H-S-T4-24VS	AEL5172S	
	LC4H-PS-R6-AC240V	AEL5317PS	
	LC4H-PS-R6-AC240VS	AEL5387PS	
	LC4H-S-R6-24V	AEL5312S	
	LC4H-S-R6-24VS	AEL5382S	
	LC4H-S-T6-24V	AEL5302S	
	LC4H-S-T6-24VS	AEL5372S	
	LC4H-PS-T4-AC240V	AEL5107PS	
	LC4H-PS-T4-AC240VS	AEL5177PS	
	LC4H-PS-T6-AC240V	AEL5307PS	
	LC4H-PS-T6-AC240VS	AEL5377PS	

Discontinuation on December 26th, 2022

Series	Model number	Part number	Recommended substitutes
LC4H-S Electronic Counter (continued)  *Includes custom-made items.	LC4H-SV-T4-24V	AEL5202S	There is no recommended replacement.
	LC4H-SV-R4-24V	AEL5212S	
	LC4H-PSV-R4-AC240V	AEL5217PS	
	LC4H-SV-T4-24VS	AEL5272S	
	LC4H-SV-R4-24VS	AEL5282S	
	LV4H-PSV-R4-AC240VS	AEL5287PS	
	LC4H-SV-T6-24V	AEL5402S	
	LV4H-SV-R6-24V	AEL5412S	
	LC4H-PSV-R6-AC240V	AEL5417PS	
	LC4H-SV-T6-24VS	AEL5472S	
	LC4H-SV-R6-24VS	AEL5482S	
	LC4H-PSV-R6-AC240VS	AEL5487PS	

Panasonic
INDUSTRY