

| | | | |
|---|---|--------------------------|------------------|
| PDN Number: | 20170303001 | PDN Date: | Mar 8, 2017 |
| Title: | Discontinuance of TSB15LV01PFC and TSB15LV01PFCG4 | | |
| Customer Contact: | PCN Manager | Dept: | Quality Services |
| Change Type: | Product Discontinuance - End Of Life | | |
| Product Discontinuance Notification Details | | | |
| Description of Discontinuance: | | | |
| Texas Instruments, Incorporated (TI) is announcing the discontinuance of the TSB15LV01PFC and TSB15LV01PFCG4. A life time buy is not being offered, nor does TI have any products that could serve as suitable replacement devices. | | | |
| NOTE: There are no samples offered for withdrawn/obsolete products. If you have any questions, please contact your local sales representative. | | | |
| Reason for Discontinuance: | | | |
| Manufacturing support is no longer available for these devices. | | | |
| Product Affected: | | | |
| Product Being Discontinued | RECOMMENDED REPLACEMENT PRODUCTS | REPLACEMENT CODES | |
| TSB15LV01PFC | None | Not Applicable | |
| TSB15LV01PFCG4 | None | Not Applicable | |
| Replacement Notes: | | | |
| F = Similar functionality but not equivalent. | | | |
| P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent. | | | |
| Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent. | | | |
| S = EXACT equivalent in functionality and parametrically to the compared device. | | | |

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

| Location | E-Mail |
|-----------------|--|
| USA | PCNAmericasContact@list.ti.com |
| Europe | PCNEuropeContact@list.ti.com |
| Asia Pacific | PCNAsiaContact@list.ti.com |
| Japan | PCNJapanContact@list.ti.com |