

PRODUCT DISCONTINUATION

PD-ION-LLSS-14

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ION	CNN	Discontinuation	Notify Distributors and Field	4/30/14

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

Due to a component end of life, the follow products will be discontinued and will no longer be able to be ordered once stock reaches 0

2990011 - RAD-80211-XDB
 2885728 - RAD-80211-XD
 2885757 - RAD-80211-XD-BUS

Below are the recommended replacements for each part. Please read the details of each replacement carefully to make sure they fit the application.

If you need assistance in choosing a replacement product, please contact Technical Service

Replacement details

2990011 – RAD-80211-XDB

	Order Number	Part Description	Serial Ports	802.11b/g	802.11a	Class I Division 2
Discontinued	2990011	RAD-80211-XDB	No	Yes	Yes	Yes
Replacement	2701093	FL WLAN 5101	No	Yes	Yes	Scheduled Q3 2014

2885728 – RAD-80211-XD

	Order Number	Part Description	Serial Ports	802.11b/g	802.11a	Class I Division 2	Bridge mode
Discontinued	2885728	RAD-80211-XD	Yes	Yes	Yes	Yes	Yes
Replacement	2900046	RAD-80211-XD/HP	Yes	Yes	No	Yes	Yes
Replacement	2701093	FL WLAN 5101	No	Yes	Yes	Scheduled Q3 2014	No



PRODUCT DISCONTINUATION

2885757 – RAD-80211-XD-BUS

	Order Number	Part Description	Serial Ports	802.11b/g	802.11a	Class I Division 2	Bridge mode	IO BUS
Discontinued	2885757	RAD-80211-XD-BUS	Yes	Yes	Yes	Yes	Yes	Yes
Replacement	2900047	RAD-80211-XD-/HP-BUS	Yes	Yes	No	Yes	Yes	Yes
Replacement	2701093	FL WLAN 5101	No	Yes	Yes	Scheduled Q3 2014	No	No

Warranty Information:

All standard and extended warranty terms will be covered. Support of the discontinued products will be available for all installations.

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? Y

Transaction Dates:

Last Buy from Phoenix Contact: Available until stock reaches 0

Last Scheduled Ship from Phoenix Contact: Available until stock reaches 0

Discontinued Part#	Type Description	Replacement Part#	Type Description
2990011	RAD-80211-XDB	2701093	FL WLAN 5101
2885728	RAD-80211-XD	2900046	RAD-80211-XD/HP
2885757	RAD-80211-XD-BUS	2900047	RAD-80211-XD/HP-BUS

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

JUSTIN SHADE
(717)944-1300x3524
jshade@phoenixcon.com

Thank you,



Ira Sharp , Product Marketing Manager