



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631
www.littelfuse.com

July 28, 2015

LF PCN# C0136 Fuse holder Alternative Material Notification

Dear Valued Customer,

Littelfuse Inc., as the leading provider of total circuit protection solution with global commitment to providing the highest quality products, would like to notify you that we have qualified an alternative material for the holder in the following fuse holder series. The intent of qualifying an alternative material is to reduce the risk of production interruptions due to material shortages. The material has been fully tested and we have PPAP documentation, available upon request.

Material	Series
OFHA000_	Inline ATO holder
OFHJ000_	Inline JCase holder
OFHM000_	Inline Mini holder
OFNY000_	Glass Inline holder
FHAC000_	Inline ATO holder
FHJC000_	Inline JCase holder
FHLM0200_	Inline Mini Add-A-Circuit holder
FHM20200_	Inline Low Profile Mini Add-A-Circuit holder
HLJC000_	Inline Low Profile JCase holder
MAHC000_	Inline Maxi holder
SFHA000_	Inline ATO holder

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have.

Thank you for your continued support.

Best Regards,

Pat Prince

Pat Prince
Associate Product Manager - Commercial Vehicle Products
p prince@littelfuse.com

LFPCNC0136 Affected Parts List

Material

0FHA0001LXN
0FHA0001SXF
0FHA0001SXJ
0FHA0001XBP
0FHA0001XP
0FHA0001XPA
0FHA0001XXFUS
0FHA0001ZXJ-GRN
0FHA0001ZXJ
0FHA0001ZXJD
0FHA0002SXJ
0FHA0002XBP
0FHA0002XP
0FHA0002XPA
0FHA0002XPFUS
0FHA0002XXFUS
0FHA0002ZXJ
0FHA0002ZXJA
0FHA0002ZXJB
0FHA0030XP
0FHA0030XPA
0FHA0030XPFUS
0FHA0030Z
0FHA0006ZXJ
0FHA0020Z
0FHA0200Z
0FHA0200ZP
0FHA0200ZPA
0FHA0200ZPFUS
0FHJ1001G
0FHJ1002G
0FHJ2001G
0FHJ2002G
0FHJ3003U
0FHJ3003UXA
0FHM0001ZXJ
0FHM0001ZX910
0FHM0001LXN
0FHM0001SXJ
0FHM0001XP
0FHM0001XPA
0FHM0001XPFUS
0FHM0001XXFUS
0FHM0001ZXJ-F7.5
0FHM0001ZXJ-RED
0FHM0001ZXJA
0FHM0001ZXJB
0FHM0002LXN
0FHM0002X-E-GM
0FHM0002X-GM
0FHM0002XP
0FHM0002XPA
0FHM0002XPFUS
0FHM0002XXFUS
0FHM0002Z

0FHM0002ZXJ
0FHM0002ZXJA
0FHM0002ZXJB
0FHM0002ZXJC
0FHM0002ZXJD
0FHM0002ZXJE
0FHM0002ZXJF
0FHM0002ZXJG
0FHM0002ZXJG-F10
0FHM0002ZXJL
0FHM0002ZXJM
0FHM0003UXJJ
0FHM0003UXJK
0FHM0003X-A-GM
0FHM0003ZXJA
0FHM0003ZXJB
0FHM0003ZXJB-F05
0FHM0003ZXJC
0FHM0003ZXJC-F10
0FHM0003ZXJD
0FHM0003ZXJE
0FHM0003ZXJF
0FHM0003ZXJG
0FHM0003ZXJH
0FHM0003ZXJK
0FHM0003ZXJP
0FHM0003ZXJP-F5
0FHM0003ZXJR
0FHM0200S
0FHM0200Z
0FHM0200Z-NC
0FHM0200ZP
0FHM0200ZPA
0FHM0200ZPFUS
0FNY0001S
0FNY0001XP
0FNY0001XPA
0FNY0001XPFUS
0FNY0001XXFUS
0FNY0001ZXJ
0FNY0001ZXJ-F14
0FNY0001ZXJ-F20
0FNY0002SXJ-F20
0FNY0002ZXJ
0FNY0002ZXJ-F30
0FNY0020XP
0FNY0020XPA
0FNY0030S
0FNY0030XP
0FNY0030XPA
0FNY0030XPFUS
0FNY0030ZXFUS
FHAC0001LXN
FHAC0001SXJ
FHAC0001XP
FHAC0001XPA
FHAC0001XXFUS

FHAC0001ZXJ
FHAC0001ZXJA
FHAC0001ZXJC
FHAC0001ZXJD
FHAC0001ZXJE
FHAC0001ZXJF
FHAC0001ZXJG
FHAC0001ZXJJ
FHAC0002LXN
FHAC0002SXJ
FHAC0002XP
FHAC0002XPA
FHAC0002XPFUS
FHAC0002XXFUS
FHAC0002ZXJ
FHAC0002ZXJA
FHAC0002ZXJC
FHAC0002ZXJD
FHAC0002ZXJE
FHAC0003ZXJA
FHAC0003ZXJB
FHJC1001FXA
FHJC1001G
FHJC1001GB
FHJC1002G
FHJC1002GA
FHJC1002GA-F60
FHJC1002GB
FHJC1002L
FHJC1002MB
FHJC1002MB-F60
FHJC2002G
FHJC2002L
FHLM0200Z
FHLM0200ZPA
FHM20200Z
FHM20200ZPA
HLJC1001G
HLJC1001GXD
HLJC1002G
HLJC2002G
MAHC0001TXJ
MAHC0001ZXJ
MAHC0001ZXJA
SFHA0001ZXJ