

## Product/Process Change Notifications



# PCN - 18 071

Amphenol Information Communication and Commercial Products Group  
[www.amphenol-icc.com](http://www.amphenol-icc.com)

Release Date: August 23 2018

<b>Product Name:</b>	Power Din Connectors	
	HPL – 556	
<b>Product Manager:</b>	Vicy Pulayath	
<b>Subject:</b>	Notification of Planned Change	
<b>Distribution:</b>	Global	
<b>Type of Change:</b>	Location Change	
<b>Change Description:</b>	Transfer of manufacturing location from Besancon, France to Cochin, India	
<b>Reason for Change:</b>	Product consolidation in Cochin, India	
<b>Affected Parts:</b>	See Attached Affected parts file	
<b>Effective Date of Change:</b>	December 17,2018	
<b>Last Time Buy Date:</b>	NA	
<b>Earliest Disty Return Date:</b>	NA	
<b>Last Time Shipment Date</b>	NA	
<b>Datasheet Attached?</b>	NA	
<b>Qual/Test Data Attached?</b>	NA	
<b>Samples Availability Date:</b>	December 17,2018	
<b>Available Alternatives?</b>		
<b>Questions?</b>	<i>Contact your local AICC Representative, or Product Manager</i>	
	Vicy Pulayath	
	+91 (484) 3391633 /Vicy.Pulayath@fci.com	

Note:  
 Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN.  
 Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date
PCN18071	5159002311193111LF	Location Change	December17,2018
PCN18071	5159002311194111LF	Location Change	December17,2018
PCN18071	5159002312354111LF	Location Change	December17,2018
PCN18071	5159002312394111LF	Location Change	December17,2018
PCN18071	5159009322354130LF	Location Change	December17,2018
PCN18071	5159009326354101LF	Location Change	December17,2018
PCN18071	5159009326354130LF	Location Change	December17,2018
PCN18071	5159009326394101LF	Location Change	December17,2018
PCN18071	5159009326394110LF	Location Change	December17,2018
PCN18071	5159009326394130LF	Location Change	December17,2018
PCN18071	5159009482354111LF	Location Change	December17,2018
PCN18071	5159009482394111LF	Location Change	December17,2018
PCN18071	5159009486354111LF	Location Change	December17,2018
PCN18071	5159009486354611LF	Location Change	December17,2018
PCN18071	5159009486394111LF	Location Change	December17,2018
PCN18071	5159009486394AAKLF	Location Change	December17,2018
PCN18071	51590291519620LF	Location Change	December17,2018
PCN18071	51590291523440LF	Location Change	December17,2018
PCN18071	51590291523448ALF	Location Change	December17,2018
PCN18071	51590291523660LF	Location Change	December17,2018
PCN18071	5159909321194110LF	Location Change	December17,2018
PCN18071	5159909481193111LF	Location Change	December17,2018
PCN18071	5159909481194111LF	Location Change	December17,2018
<b>Count:</b>	<b>23</b>		





