



Product Change Notification

TE Connectivity

Product Change Notification: E-17-012194

PCN Date: 22-AUG-17


TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DEUTSCH DRC16-40S, DRC18-40SX, DRC26-40SX

Description of Changes
The Industrial & Commercial Transportation (ICT) business unit of TE Connectivity (TEC) is adding an alternate raw material supplier for DRC connectors listed below which are made from PPS 40GF and manufactured in ICT-Empalme, Sonora (MX) campus. The product will be identified by a small single dot molded on the side of the housing near the part number. Also, the packaging box will have an orange sticker dot for easy identification. See photo below. TEC-ICT will do its due diligence by requiring a PPAP from the supplier. This supplier has been used in the past by TEC business unit with excellent performance. This change is effective immediately to prevent shipment delays. See attached advance notification letter.

Warning: Please check-in ONLY Class 1 Documents / Files Note: Images shown on this page are not actual size. Please use the Preview page to view actual image size. Alternate Material ID Location (DRC16040S shown as example)

Alternate Material ID



Alternate Material ID Location on Box
Alternate Material ID



Other attachments:
[Advance Notification Letter](#)

Reason for Changes:
Dear Customer, we inform you immediately of this alternate supplier as part of our aggressive continuous improvement efforts on delivery. The alternate supplier process is executed by following TE internal strict procedures, which mitigates quality risk while increasing our ability to supply your products on time. The alternate supplier is governed under a TS16949 certified quality management system per standard automotive requirements. An internal release based on our specifications will be executed before any parts are delivered.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-SEP-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DRC16-40S	NO			"ZPF000000000131293", "DRC16-40S-LS", "ZPF000000000146159", "DRC16-40S-L"			
DRC16-40SE	NO			"ZPF000000000131295"			
DRC18-40SA	NO			"ZPF000000000131296"			
DRC18-40SAE	NO			"ZPF000000000131298"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DRC26-40SA	NO			"ZPF000000000131316", "DRC26-40SA-LS", "DRC26-40SA-L"			
DRC26-40SA-L011	NO			"ZPF000000000131317", "\$\$DRC26-40SA-L011"			
DRC26-40SB	NO			"ZPF000000000131320"			
DRC26-40SB-L011	NO			"ZPF000000000131321", "\$\$DRC26-40SB-L011"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DRC16-40S	NO			"ZPF000000000131293", "DRC16-40S-LS", "ZPF000000000146159", "DRC16-40S-L"			
DRC26-40SA	NO			"ZPF000000000131316", "DRC26-40SA-LS", "DRC26-40SA-L"			
DRC26-40SA-L011	NO			"ZPF000000000131317", "\$\$DRC26-40SA-L011"			
DRC26-40SB	NO			"ZPF000000000131320"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DRC16-40S	NO			"ZPF000000000131293", "DRC16-40S-LS", "ZPF000000000146159", "DRC16-40S-L"			
DRC26-40SA	NO			"ZPF000000000131316", "DRC26-40SA-LS", "DRC26-40SA-L"			
DRC26-40SA-L011	NO			"ZPF000000000131317", "\$\$DRC26-40SA-L011"			
DRC26-40SB	NO			"ZPF000000000131320"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DRC16-40SE	NO			"ZPF000000000131295"			
DRC18-40SA	NO			"ZPF000000000131296"			
DRC18-40SAE	NO			"ZPF000000000131298"			
DRC26-40SA	NO			"ZPF000000000131316", "DRC26-40SA-LS", "DRC26-40SA-L"			
DRC26-40SA-L011	NO			"ZPF000000000131317", "\$\$DRC26-40SA-L011"			
DRC26-40SB-L011	NO			"ZPF000000000131321", "\$\$DRC26-40SB-L011"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DRC16-40SE	NO			"ZPF000000000131295"			
DRC18-40SA	NO			"ZPF000000000131296"			
DRC18-40SAE	NO			"ZPF000000000131298"			
DRC26-40SA	NO			"ZPF000000000131316", "DRC26-40SA-LS", "DRC26-40SA-L"			
DRC26-40SA-L011	NO			"ZPF000000000131317", "\$DRC26-40SA-L011"			
DRC26-40SB-L011	NO			"ZPF000000000131321", "\$DRC26-40SB-L011"			