



Product Change Notification

TE Connectivity

Product Change Notification: PCN-22-125590

PCN Date: 03-JAN-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH DT, DTM, DTMH, DTP, HD Components Manufacturing Location Change.

Description of Changes

DEUTSCH DT, DTM, DTMH, DTP, HD Components Manufacturing Location Change. The Industrial and Commercial Transportation business unit of TE Connectivity is transferring components of the following part numbers from Empalme, SON, MEX to Tecate, BC, MX. These PNs are TE proprietary designs, therefore considered catalog/general market product. TE reserves the right to move assembly back to prior location/supplier based on business need. A Level IV PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:

PCN Attributes:

Product Category:	Kind of Change:
Connector Housings	Location Change
Change Feature:	Potential Customer Impact:
No Feature Change	Localization
Remarks:	

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
---	---

	11-MAR-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT04-4P-CL03	NO						
DT04-4P-L012	NO						
DT04-4P-LE11	NO						
DTM04-12PA-L012	NO			"ZPF000000000130570"			
DTM04-12PB-L012	NO			"ZPF000000000130572"			
DTM04-2P-E003	NO			"ZPF000000000130132", "8202607906"			
DTM04-2P-E005	NO			"ZPF000000000130134"			
DTM04-2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10-AS"			
DTM04-2P-P006	NO			"ZPF000000000130137"			
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
DTM04-4P-E003	NO			"ZPF000000000130264"			
DTM04-4P-E004	NO			"ZPF000000000130265"			
DTM04-4P-E005	NO			"ZPF000000000130266"			
DTM06-2S-E003	NO			"ZPF000000000130141"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTM06-2S-E005	NO			"ZPF000000000130143"			
DTM06-2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10-AS", "DTM06-2S-EP10-LS", "DTM06-2S-EP10-L"			
DTM06-2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006-LS", "DTM06-2S-P006-L"			
DTP04-2P-E003	NO			"ZPF000000000130148", "DTP04-2P-E003-LS", "DTP04-2P-E003-L"			
DTP04-4P-L012	NO			"ZPF000000000130274"			
DTP06-2S-E003	NO			"ZPF000000000130151", "DTP06-2S-E003-LS", "DTP06-2S-E003-L"			
HD10-3-96P	NO			"ZPF000000000130253"			
HD14-3-96P	NO			"ZPF000000000130255"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTM04-2P-E003	NO			"ZPF000000000130132", "8202607906"			
DTM04-2P-E005	NO			"ZPF000000000130134"			
DTM04-2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10-AS"			
DTM04-4P-E004	NO			"ZPF000000000130265"			
DTM04-4P-E005	NO			"ZPF000000000130266"			
DTM06-2S-E005	NO			"ZPF000000000130143"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTM06-2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10-AS", "DTM06-2S-EP10-LS", "DTM06-2S-EP10-L"			
DTM06-2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006-LS", "DTM06-2S-P006-L"			
DTP04-2P E003	NO			"ZPF000000000130148", "DTP04-2P-E003-LS", "DTP04 2P E003 L"			
HD10-3-96P	NO			"ZPF000000000130253"			
HD14-3-96P	NO			"ZPF000000000130255"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTM04-2P-E003	NO			"ZPF000000000130132", "8202607906"			
DTM04-2P-E005	NO			"ZPF000000000130134"			
DTM04-2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10-AS"			
DTM04-4P-E004	NO			"ZPF000000000130265"			
DTM04-4P-E005	NO			"ZPF000000000130266"			
DTM06-2S-E005	NO			"ZPF000000000130143"			
DTM06-2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10-AS", "DTM06-2S-EP10-LS", "DTM06-2S-EP10-L"			
DTM06-2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006-LS", "DTM06-2S-P006-L"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTP04-2P-E003	NO			"ZPF000000000130148", "DTP04-2P-E003-LS", "DTP04-2P-E003-L"			
HD10-3-96P	NO			"ZPF000000000130253"			
HD14-3-96P	NO			"ZPF000000000130255"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT04-4P-L012	NO						
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT04-4P-CL03	NO						
DT04-4P-L012	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DT04-4P-LE11	NO						
DTM04-12PA-L012	NO			"ZPF000000000130570"			
DTM04-12PB L012	NO			"ZPF000000000130572"			
DTM04-2P-E003	NO			"ZPF000000000130132", "8202607906"			
DTM04-2P-E005	NO			"ZPF000000000130134"			
DTM04-2P-EP10	NO			"ZPF000000000130136", "DTM04-2P-EP10-AS"			
DTM04-2P-P006	NO			"ZPF000000000130137"			
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
DTM04-4P-E003	NO			"ZPF000000000130264"			
DTM04-4P-E004	NO			"ZPF000000000130265"			
DTM04-4P-E005	NO			"ZPF000000000130266"			
DTM06-2S-E003	NO			"ZPF000000000130141"			
DTM06-2S-EP10	NO			"ZPF000000000130140", "DTM06-2S-EP10-AS", "DTM06-2S-EP10-LS", "DTM06-2S-EP10-L"			
DTM06-2S-P006	NO			"ZPF000000000130146", "DTM06-2S-P006-LS", "DTM06-2S-P006-L"			
DTP04-2P-E003	NO			"ZPF000000000130148", "DTP04-2P-E003-LS", "DTP04-2P-E003-L"			
DTP04-4P-L012	NO			"ZPF000000000130274"			
DTP06-2S-E003	NO			"ZPF000000000130151", "DTP06-2S-E003-LS", "DTP06-2S-E003-L"			
HD10-3-96P	NO			"ZPF000000000130253"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HD14-3-96P	NO			"ZPF000000000130255"			