

## IloT Product Change Notice

The change will be applied on the BB-USO9ML2-A standard model. If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

- Reason for the Change:** EOL component.
- Affected Products:** BB-USO9ML2-A and custom variations. DTOS customer notified separately.
- Impact on Application:** No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No
Physical Outlook Change	No
Ordering P/N Change	No
Cut-in Implement	Component Running Change

#### 4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
BB-USO9ML2-A	SP211EHCT-L/TR (MaxLinear / Exar)	SP3243EUEA-L/TR (MaxLinear / Exar)	IC / Part – RS-232 transceiver	None	The manufacturer discontinued SP211EHCT-L/TR.

#### 5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
BB-USO9ML2-A	ECOM-178633	8/15/2021	Running Change	Add new PCBA as an alternate to the old PCBA.

\*Note: Cut-in progress depends on factory production schedule, listed in this table is an ESTIMATED time-frame.

### Contact Windows

PM	Brian Foster / <a href="mailto:brian.foster@advantehc.com">brian.foster@advantehc.com</a>
AE	Chris Politsch / <a href="mailto:Chris.Politsch@advantech.com">Chris.Politsch@advantech.com</a>