



# Product Change Notification

Current Date: 15-Feb-2023

## TE Connectivity

Product Change Notification: PCN-22-129095

PCN Date: 09-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description: (Text limited to 120 characters)**

RM & MT relay

**Description of Changes**

The listed part numbers are being discontinued and no longer available. Please consult with your local Customer sales representative in case of open questions related to open orders.

**Reason for Changes:**

**PCN Attributes:**

|                               |                                   |
|-------------------------------|-----------------------------------|
| <b>Product Category:</b>      | <b>Kind of Change:</b>            |
| Relays, Contactors & Switches | Status Change                     |
| <b>Change Feature:</b>        | <b>Potential Customer Impact:</b> |
| Discontinuance                | Spare Part Availability           |
| <b>Remarks:</b>               |                                   |

**Estimated Dates:**

|   |   |
|---|---|
| <b>Last Order Date (Obsolete Parts Only):</b>                 | <b>First Ship Date of Changed Items (Changed Parts Only):</b> |
| 10-FEB-2022   |   |
| <b>Last Ship Date of Changed Items (Obsolete Parts Only):</b> | <b>Last Date for Mixed Shipments: (Changed Parts Only):</b>   |
| 31-JUL-2022   | No Mixed Shipments  |
| <b>Effectivity Date:</b>                                      | <b>Date of First Samples:</b>                                 |

**Part Number(s) being Modified:**

| Part Number                 | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s)                            | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1393092-2</a>   | YES                       |                  | A91443-000,AMPS-0-1393092-2,<br><b>MT326230</b> |                        |                                 |                           |
| <a href="#">1393092-4</a>   | YES                       |                  | CE0509-000,AMPS-0-1393092-4,<br><b>MT328024</b> |                        |                                 |                           |
| <a href="#">1393092-7</a>   | YES                       |                  | CE0510-000,AMPS-0-1393092-7,<br><b>MT328115</b> |                        |                                 |                           |
| <a href="#">1393092-8</a>   | YES                       |                  | CE0511-000,AMPS-0-1393092-8,<br><b>MT328230</b> |                        |                                 |                           |
| <a href="#">4-1393090-9</a> | YES                       |                  | CE0523-000,AMPS-4-1393090-9,<br><b>MT221012</b> |                        |                                 |                           |
| <a href="#">5-1393090-0</a> | YES                       |                  | CE0524-000,AMPS-5-1393090-0,<br><b>MT221024</b> |                        |                                 |                           |
| <a href="#">5-1393090-3</a> | YES                       |                  | CE0527-000,AMPS-5-1393090-3,<br><b>MT221110</b> |                        |                                 |                           |
| <a href="#">5-1393090-4</a> | YES                       |                  | CE0528-000,AMPS-5-1393090-4,<br><b>MT221220</b> |                        |                                 |                           |
| <a href="#">5-1393090-7</a> | YES                       |                  | CE0529-000,AMPS-5-1393090-7,<br><b>MT223024</b> |                        |                                 |                           |
| <a href="#">6-1393090-3</a> | YES                       |                  | CE0530-000,AMPS-6-1393090-3,<br><b>MT226012</b> |                        |                                 |                           |
| <a href="#">6-1393090-4</a> | YES                       |                  | CE0531-000,AMPS-6-1393090-4,<br><b>MT226024</b> |                        |                                 |                           |
| <a href="#">6-1393090-5</a> | YES                       |                  | CE0532-000,AMPS-6-1393090-5,<br><b>MT226048</b> |                        |                                 |                           |

| Part Number                 | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s)                            | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">6-1393090-7</a> | YES                       |                  | CE0533-000,AMPS-6-1393090-7,<br><b>MT226115</b> |                        |                                 |                           |
| <a href="#">6-1393090-8</a> | YES                       |                  | CE0534-000,AMPS-6-1393090-8,<br><b>MT226230</b> |                        |                                 |                           |
| <a href="#">6-1393090-9</a> | YES                       |                  | CE0535-000,AMPS-6-1393090-9,<br><b>MT228024</b> |                        |                                 |                           |
| <a href="#">6-1393091-5</a> | YES                       |                  | A34386-000,AMPS-6-1393091-5,<br><b>MT3210C4</b> |                        |                                 |                           |
| <a href="#">6-1393091-8</a> | YES                       |                  | CE0536-000,AMPS-6-1393091-8,<br><b>MT321012</b> |                        |                                 |                           |
| <a href="#">7-1393090-1</a> | YES                       |                  | CE0540-000,AMPS-7-1393090-1,<br><b>MT228230</b> |                        |                                 |                           |
| <a href="#">7-1393091-0</a> | YES                       |                  | E40371-000,AMPS-7-1393091-0,<br><b>MT321024</b> |                        |                                 |                           |
| <a href="#">7-1393091-1</a> | YES                       |                  | CE0541-000,AMPS-7-1393091-1,<br><b>MT321048</b> |                        |                                 |                           |
| <a href="#">7-1393091-2</a> | YES                       |                  | CE0542-000,AMPS-7-1393091-2,<br><b>MT321060</b> |                        |                                 |                           |
| <a href="#">7-1393091-9</a> | YES                       |                  | CE0545-000,AMPS-7-1393091-9,<br><b>MT3230C4</b> |                        |                                 |                           |
| <a href="#">7-1415544-3</a> | YES                       |                  |   |                        |                                 |                           |
| <a href="#">8-1393091-4</a> | YES                       |                  | CE0553-000,AMPS-8-1393091-4,<br><b>MT323024</b> |                        |                                 |                           |
| <a href="#">8-1393091-9</a> | YES                       |                  | <b>MT323110</b>                                 |                        |                                 |                           |
| <a href="#">9-1393091-7</a> | YES                       |                  | D72191-000,AMPS-9-1393091-7,<br><b>MT326024</b> |                        |                                 |                           |
| <a href="#">9-1393091-8</a> | YES                       |                  | CE0559-000,AMPS-9-1393091-8,<br><b>MT326048</b> |                        |                                 |                           |