


Light is OSRAM

Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048)
OS-PDN-2020-029

04 May 2020

Last order:	04 December 2020
Last delivery:	04 June 2021



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
G2LS T036.702700QPXX1	Q65112A8009	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.703000QPXX1	Q65112A8008	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.704000QPXX1	Q65112A8007	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.704000QPXX1	Q65112A8007	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.705000QPXX1	Q65112A8004	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.802700QPXX1	Q65112A8003	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.803000QPXX1	Q65112A8002	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.804000QPXX1	Q65112A8006	Level 2	No sufficient future volume forecast	n/a		
G2LS T036.805000QPXX1	Q65112A8005	Level 2	No sufficient future volume forecast	n/a		

Products Affected by Product Discontinuation Notification

Number: OS-PDN-2020-029

Name: Product Discontinuation with No Replacement

Release Date: 5/4/2020

Last Order: 12/4/2020

Last Delivery: 6/4/2020

DISCONTINUED

NEW (REPLACEMENT)

<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>	<i>Product</i>	<i>QNumber</i>	<i>QNumber Description</i>	<i>Part Number</i>
G2LS T036.7	Q65112A8009	G2LS T036.702700QPXX1					
G2LS T036.7	Q65112A8008	G2LS T036.703000QPXX1					
G2LS T036.7	Q65112A8007	G2LS T036.704000QPXX1					
G2LS T036.7	Q65112A8004	G2LS T036.705000QPXX1					
G2LS T036.8	Q65112A8003	G2LS T036.802700QPXX1					
G2LS T036.8	Q65112A8002	G2LS T036.803000QPXX1		No Replacem		No Replacement	
G2LS T036.8	Q65112A8006	G2LS T036.804000QPXX1					
G2LS T036.8	Q65112A8005	G2LS T036.805000QPXX1					