

M/A-COM Technology Solutions Inc.
100 Chelmsford Street
Lowell, Massachusetts 01851
www.macom.com

MACOM[™]
Partners from RF to Light

10 November 2015

Digi-Key Corporation
701 Brooks Ave South
Thief River Falls, Minnesota 56701


ATTN: Quality/Purchasing Manager

Subject: MADP-000235-10720T Marking Change

PCN #: PCN-00794

Dear Valued Customer:

As part of MACOM's continual improvement program, we are making a marking change on the MADP-000235-10720T in order to improve the readability of the cathode mark. We will be changing from a black cathode dot to a black cathode slash.



Current cathode dot mark

New cathode slash mark

All specifications and standards remain unchanged. These changes will not affect form, fit, function or reliability. Product incorporating changes will begin shipping in January 2016.

In accordance with M/A-COM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased this product in the previous two years.

Sincerely,

Loren Reifsteck
U.S. Quality Manager
M/A-COM Technology Solutions, Inc.
Tel: +1-978-656-2481
E-mail: loren.reifsteck@macom.com