



<b>Title of Change:</b>	Product Discontinuance of AMIS30621AUA
<b>Last Time Buy Date:</b>	31 August 2017
<b>Last Ship Date:</b>	15 January 2018
<b>Contact information:</b>	Contact your local ON Semiconductor Sales Office or <PCN.Support@onsemi.com >
<b>Type of notification:</b>	Customers must notify ON Semiconductor (<PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

**Description and Purpose:**

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products and the products will no longer be available.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

## Additional contacts are:

## Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

## Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

## Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 5817 1060

Japan

## Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

**List of affected Standard Parts:**

Device to be Discontinued	Recommended Replacement	Supplier
AMIS30621AUA	NONE	NONE