

TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc.
10 N. Martingale Rd.
Schaumburg, IL 60173
Tel (630) 237-2405 Fax (847) 240-1715
<http://www.t-yuden.com>

Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors

DATE: June 14th, 2019

RE: Discontinuation of Leaded Common Mode Choke Coils: TLF10UAH_ & TLH10UAH_ Series

REF NO.: UTY-DN19-03D

Taiyo Yuden (U.S.A.) Inc. hereby notifies that the following part numbers are to be discontinued immediately from the issue of this notice for all Taiyo Yuden (U.S.A) Inc distributors. There is no sales history for these parts; therefore, no last orders will be accepted.

Discontinued Part Numbers
TLF10UAH1230R5
TLF10UAH8720R7
TLF10UAH9920R6
TLH10UAH1230R5
TLH10UAH8720R7
TLH10UAH9920R6

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department