



Product Change Notification

TE Connectivity

Product Change Notification: E-15-011034

PCN Date: 27-JUL-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
HD-22 Board Mount Connectors

Description of Changes
The following part numbers are being discontinued (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant differences described. Please verify all substitute or alternate part numbers provided are suitable for your specific application. Drawings are available via TE.com.

Reason for Changes:
Discontinuance. Low/No Sales

Estimated Dates:

| | |
|---|--|
| Last Order Date (Obsolete Parts Only): 30-OCT-2015 | First Date To Ship (Changed Parts Only): |
| Last Ship Date (Obsolete Parts Only): 30-NOV-2015 | Last Date for Mixed Shipments: (Changed Parts Only): No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5750489-1 | YES | | | | 5749798-1 ,5749798-1 | | Does not have boardlock |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Number | Related Part Number | Customer Part Number | Current Revision | New Revision |
|-------------------------|---------------------|----------------------|------------------|--------------|
| 5750489 | 5750489-1 | | B2 | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5750489-1 | YES | | | | 5749798-1 | | Does not have boardlock |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 5750489-1 | YES | | | | 5749798-1 | | Does not have boardlock |

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The last Order Date, last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

| Drawing Number | Related Part Number | Customer Part Number | Current Revision | New Revision |
|-------------------------|---------------------|----------------------|------------------|--------------|
| 5750489 | 5750489-1 | | B2 | |