



Product Change Notification

TE Connectivity

Product Change Notification: E-17-007364

PCN Date: 20-JUN-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
 OMI relay marking

Description of Changes
 OMI relay marking cancel SEMIKO
 Other attachments:
[Change explaining](#)

Reason for Changes:
 Manufacturing / Process Requirements. OMI relay SEMIKO certificate invalid, not going to be renewed, and VDE can cover SEMIKO.
 Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	30-OCT-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	24-NOV-2017

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1419122-6	NO			"OMI-SH-112LM,000"			
2-1461183-8	NO			"OMI-SH-112LM,601"			
3-1440000-8	NO			"OMI-SH-112D,394"			
4-1440000-0	NO			"OMI-SH-112L,394"			
4-1440000-1	NO			"OMI-SH-112LM,394"			
5-1419122-2	NO			"OMI-SS-112DM,000"			
5-1419122-3	NO			"OMI-SS-112L,000"			
5-1440000-6	NO			"OMI-SS-112L,300"			
6-1419122-0	NO			"OMI-SS-124L,000", "OMI-SS-124L.000"			
6-1419122-2	NO			"OMI-SS-124LM,000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-1440000-8	NO			"OMI-SH-112D,394"			
4-1440000-0	NO			"OMI-SH-112L,394"			
5-1440000-6	NO			"OMI-SS-112L,300"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-1440000-8	NO			"OMI-SH-112D,394"			
4-1440000-0	NO			"OMI-SH-112L,394"			
4-1440000-1	NO			"OMI-SH-112LM,394"			
5-1419122-3	NO			"OMI-SS-112L,000"			
5-1440000-6	NO			"OMI-SS-112L,300"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-1440000-8	NO			"OMI-SH-112D,394"			
4-1440000-0	NO			"OMI-SH-112L,394"			
5-1419122-2	NO			"OMI-SS-112DM,000"			
6-1419122-0	NO			"OMI-SS-124L,000", "OMI-SS-124L,000"			
6-1419122-2	NO			"OMI-SS-124LM,000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1440000-1	NO			"OMI-SH-112LM,394"			
5-1419122-3	NO			"OMI-SS-112L,000"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1419122-6	NO			"OMI-SH-112LM,000"			
2-1461183-8	NO			"OMI-SH-112LM,601"			
3-1440000-8	NO			"OMI-SH-112D,394"			
4-1440000-0	NO			"OMI-SH-112L,394"			
4-1440000-1	NO			"OMI-SH-112LM,394"			
5-1419122-2	NO			"OMI-SS-112DM,000"			
5-1419122-3	NO			"OMI-SS-112L,000"			
6-1419122-0	NO			"OMI-SS-124L,000", "OMI-SS-124L,000"			
6-1419122-2	NO			"OMI-SS-124LM,000"			